

Renewal 521 / 519 T315 R2-1W

Found:

30" car Tree Now Dead snag

18" D. Fir Now stump N74W 20±
Bank scribed 1/5

30' D. Fir Now dead snag N10E 30±
Shows good Scar
opened tree for scribe "BT"
I find distance to be 39±

Renewed:

Along The South side of car
Tree
Set Brass cap MFD,
county Surveyors office

T315

1/5 R 24/519 R
1/5 W W

1966

New Bearing Trees:

9" W. Fir N29 W 94±
scribed 1/5 21 CS BT

12" W. Fir S. 59 E 13±
scribed 1/5 19 CS BT

7-12-66

[Handwritten signature]

521-RW
524-R2W
S.V. J.V.B.

C.S. No. 54/28-40

DIETZEN NO. 385-G