

Renewal S36 only T3/SR2W

Found:

16" Fir Stump N55E 35E

Faint scribe visible "5" "3"

I find this bearing to be N50E

14" D. Fir Now 24" N75W 16E

Shows a good scar.

No Trace of cor. stone

Renewed:

Set brass cap at  $\frac{1}{4}$  section ~~112~~

county surveyors office

T3/SR2W

$\frac{1}{4}$ A

S36

T323

1966

New Bearing Tree

4" D. Fir N27 $\frac{1}{2}$ E 142

scribed  $\frac{1}{4}$  S36 CS BT

7-21-66

~~J. G. [Signature]~~  
~~[Signature]~~

472 T31-2

X# 12 T32-2

C. S. File No. 54/28-47

DIETZGEN NO. 385-6