

Renewal S11/S12 S74/S73 T31S R6W

Found (82)
8" cor. tree now stub under down 36" Fir
Scars visible on west side

10" D. Fir now 50" g S45E 19'
Shows good Scar.

10" D. Fir now 15" S60W 7'
Shows good Scar

12" Laurel now 8" N72E 42'
Shows old scar Rotten center

No trace of 8" Laurel N25W 14'

Renewed
Set Brass cap for wit. cov. MKD
county surveyors office
T31S R6W

S11/S12
S74/S73
1966

New Bearing Trees

6" cedar N54W 25'
Scribed T31S R6W S11 CS BT

10" Laurel N22 1/2 E 36'
Scribed T31S R6W S12 CS BT

No Trees in S.E. Quad

This cov lies in patch in
large blow down 122' East of
Roofs. Also about 125' North
of small Ravine running N.E.

9-27-66
J. W. B.
C. S.

* 95 O.K. S.W.B.

C. S. File No. 54/31-8

DIETZEN NO. 389-6