

Removal

$\frac{512}{213}$

T315 R9W

Found:

60" D. Fir NW SW stump N25E 10E
Shows good scars

25" W. Fir NW SW Road S45W 6E
Same be visible "1/4"

Removal:

Set Brass cap at 1/4 cor NW SW
County Surveyors office
T315 R9W

$\frac{1}{4} \frac{512}{213}$
1967

New Bearing Traces:


90 W. Fir NW SW N54E 52E
Scribed 1/4 S12 CS BT

FILED
Scribed 1/4 S13 CS BT
RECEIVED

3-17-67

MAR 17 1967

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.



X#97

O.K. J.W. B.C.S. File No. 54/323A

DIETZGEN NO. 388-6