

Renewal 19/20 T312 R9W

Ford

6" D. Fir car Tree N 12" shows good scar

8" L.O. New 9" N 15W 7' Scar is visible S 19 1/4

N.W. BT Down + Rotted

Renewal

Set Brass cap on north edge of car Tree MKD

County Surveyors office

T315 R9W

1/4 S 19 / S 20

1967

New Bearing Tree

27" D. Fir S 42 E 21' Scar is 1/4 S 20 CS BT

3-31-67

FILED
RECEIVED

MAR 31 1967

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

#109
*O

O.N. J.W.S.

C. S. File No. 54/32-57

DIETZGEN NO. 385-6