

Recovery

AP

T 31 S R 9 W  
T 32 S R 9 W

Found:

18" D. Fir cor Tree NW 21"  
opened RP RT visible

28" D. Fir NW 34" S 77 E 92  
Shows good scar

30" D. Fir NW 36" S 87 W 92  
Shows good scar.

Recovery.

Set  $\frac{3}{4}$ " x 30" on North side  
of cor Tree

All Bearing Trees Tagged &  
OK

Note:

This R.P. lies 38° East  
of  $\frac{1}{4}$  cor of sec 2 only  
T 32 S R 9 W which is Brass cap  
and in good shape.

FILED

RECEIVED

7-26-67

*J. W. B.*  
*J. C. B.*

APR 26 1967

COUNTY SURVEYOR  
DOUGLAS COUNTY, ORE.

\* 14-132-9

#133

O.K. J.W.B.

C.S. File No. 54/3270

DIETZGEN NO. 385-6