

RENEWAL $\frac{1}{4}$ S21 | S22 T31S R9W

RN# 8

Found: 1 ORIG. BT

7/8 HEX ROD AT CORNER MKD

ORIG. 24" FIR NOW 26" SNA9 S57W 45 ± FT

Shows Good SCRIBE (S)

96" D FIR NOW 10 N29 $\frac{1}{2}$ W 168 ± FT

Shows Good FACE (NOTE IF FINE TO BE 10")

6" D FIR NOW 10" N35E 41 ± FT

Shows Good FACE

RENEWAL:

SET BRASS GAP AT CORNER MKD

COUNTY SURVEYOR'S OFFICE

T31S R9W

$\frac{1}{4}$ S21 | S22

1967

NOTE:

CORNER LIES ON STEEP SOUTH
SLOPE.

4-27-67

FWJ

JCE

DIETZGEN NO. 385-6

#122

O.K. J.W.B.

C.S. File No. 54/32-71