

Renewed

$\frac{528}{533}$

T31S R3W

56" D. Fir Now 56" N55E 25'
Faint $\frac{1}{4}$ and notch at bottom
of face

Distance is from base of tree
No trace of

9" Laurel South 9'

Renewed

Set brass cap of $\frac{1}{4}$ cor MTD
county surveyors office
T31S R3W

$\frac{1}{4}$ $\frac{528}{533}$

1966

9" Laurel South 26'
scribed $\frac{1}{4}$ S 33' 25' RT

Reblazed & Rescribed

56" D. Fir N55E 23'
Distance to center
scribed $\frac{1}{4}$ S 20' 25' RT

1-16-67

[Handwritten signature]

* #27

C. S. File No. 54/36-59

DIETZGEN NO. 388-6

Remains 1 1/2 1/2 1/2 1/2

5 1/2" D. Fir NW 56" N55E 25'
Faint 1/4 and notch at bottom
of face

Distance is from face of tree

No trace of

9' Laurel South 72

Remains

Set line up at corner ASD

County Surveyors office
73 1/2 1/2 1/2

1/4 528
533

1966

9' Laurel South 267
scribed 1/4 S33 CS BT

Reblaced & Rescribed

5 1/2" D. Fir N55E 27'
Distance to center
scribed 1/4 S20 CS BT

1-6-67

[Handwritten signature]

DIETZEN NO. 385-6

* #27

C. S. File No. 54/36-59

**FILED
RECEIVED**

JAN 6 1967

**COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.**