

Renewal

36/31

T32SP8-7W

Found: ARTS

28 Pine NW 1/4 stak N57E 339

36" Pine NW 1/4 stak N20W 52

39" Fir NW 1/4 stak S15E (P. 1520E) 702

Also old stone set with 6 Grooves on the N-E-W Faces. (orig?) at corner,

I find NO good orig evidence of this cor. However by carefully chaining between the closing cor. of T32SP8-7W which is 417 1/2 ft. and find the trees of the right type & size fitting good for bearings & dist. I renew.

Renewal

Set Brass cap at sec cor MAR

County Surveyors office

T32S

R		1P
B	36/31	7
W	51	W

T33S

1968

New Bearing Trees:

6" SPINE WEST 20 FT
SCRIBED (332 CS BT)

6" SPINE N60E 17 1/2 FT
SCRIBED (331 CS BT)

10" Y PINE S15E 37 1/2 FT

SCRIBED (T33S R SW S15E BT)

22-1231P
#12-122-1
259-122-B.H.

J.W. S. S. File No. 5486-121

3-22-68
V.M.G.

DIETZEN NO. 3886-6

**FILED
RECEIVED**

MAR 25 1968

**COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.**