

Removal 528/527 T293 RBW

Found:

20" Fir diam 18" N57 $\frac{1}{2}$ E 10 $\frac{1}{2}$   
Bark scabbed  $\frac{1}{4}$  527 7295 BT

4" Fir diam 17" S18W 20 $\frac{1}{2}$   
Shrubs good scars leaning badly

No trace of orig trees

Removal:

Set Brass cap at  $\frac{1}{4}$  cor 1940

county Surveyors office

T293 RBW

$\frac{1}{4}$  528/527

1967

8" diam Fir diam 5 $\frac{1}{2}$ " N 120 $\frac{1}{2}$ E 12 $\frac{1}{2}$   
scabbed  $\frac{1}{4}$  520 CS BT

28" diam Fir diam 70" N 70E 21 $\frac{1}{2}$   
scabbed  $\frac{1}{4}$  527 CS BT

(Removal #33)

4-19-67

J.M.D.  
J.C.S.

\*#137  
D.W. J.W.B.

C.S. File No. 54/38-20