

T25 S

R22 W

532

Renewal

56/55

T26 S

Found

cor Tree broken stub

24" D.F.V New down S68E 99E

shows good scar -

14" D.F.V New down S30W 27E

Renewal

set Brass cap on side of

cor stump (14") NAD.

county surveyors office

T25 S R22 W

532

56/55

T26 S

1972

New Bearing Trees

17" D.F.V N19 1/2 W 8 E

scribed T25 S R22 W S32 45 BT

15" D.F.V S75 W 35 0

scribed T26 S R22 W S6 25 BT

#92-T25-2

#97-T26

(over)

C.S. File No.

54/40-200

DIETZGEN NO. 385-5

No Trees To go to The
SW because of Rock
Bluff. Directly south of
cor. Approx 15' High.

7-3-72

JMD
LEW

OK.
JMD