

Renewal

25 30
36 31

T30S R 2-1 W

Found:

36" D. Fir N 10 W 10", S 45 E 5 P
Back Scribe Visible T30S R 1 W S 30
good Scar for "BT"

18" D. Fir N 40 W Blaw 10 W 10 N 25 W 11 E
No Trace of SW or NE BT's

Renewal

Set Brass cap at sec cor NW 10
County Surveyors office

T30S

R	S 25 1 S 30	R
2	S 36 1 S 31	1
W		W

1968

New Bearing Trees

11" W Fir N 71 W 17 E
Scribed T30S R 2 W S 25 CS BT

16" Yew N 37 E 61 E
Scribed T30S R 1 W S 30 CS BT

12" Yew S 50 E 77 E
Scribed T30S R 1 W S 31 CS BT

No Trees Available in SW Quad.

2-6-68

~~J.W.D.~~
~~J.W.D.~~
~~J.W.D.~~

#58

#102-T30SW O.K. J.W.D.

S. File No. 54/59-62

DIETZGEN NO. 385-6