

Reverial

9/10

T305 R1W

Found

12" P. Fir now down S 91 W 36 1/2
Tree opened scribble visible 5" x 7"

Found a slope approx size with 3 notches
out of ground. I find no place
where it is from, as car falls in
cut trail. No trace of SE BT

Reverial

using 1 Bearing & Dist
I set Brass cap MND

county Surveyors office

T305 R1W

53

S9 | S10

CC

1969

New Bearing Trees

10' cedar S 67 W 49 1/2 S9
scr. bed T305 R1W S9 CC CS BT
18' Doug Fir S 62 E 38 1/2 S10
scr. bed T305 R1W S10 CC CS BT

8-15-69

O.K.
J.W.G.

120

C. S. File No.

54/59-120