

Renewal 52/51 T32S R8W

Found:

14x10x6 Stone at  $\frac{1}{4}$  cor  
chisel marks visible  
Stone firmly in ground  
62" S. Side N40W53" S79g N25W 75<sup>°</sup>E

18" S. Pine Now 36" N16E 69<sup>°</sup>E  
shows scar.

Renewal:

Set Brass cap at  $\frac{1}{4}$  cor N16E  
county Surveyors office

T32S R8W

$\frac{1}{4}$  52/51

1968

New Bearing Trees

6" Live Oak N10W 20<sup>°</sup>E  
scribed  $\frac{1}{4}$  52 CS BT

7" Live Oak S27E 22<sup>°</sup>E  
scribed  $\frac{1}{4}$  51 CS BT

Note This cor lies on fairly  
steep west slope.

3-9-68

*[Handwritten signature]*

DIETZGEN NO. 3855-6

#62

O.K. J.W.B. C.S. No. 57/365

52