

33/31

T 31 S
T 32 S R1W

Renewal
(Renewal #2)
Found

28" D.F. Now 32" almost dead N45E 29'
Shows good scar

10" D.F. Now burnt stub S70E
Faint burnt Scar visible T3 S B

12" Maple now dead N25W 19'
Rotten face and axe marks & faint marks

Did not find cor stone

Renewal:

This car now lies on east edge of
ELA except in dangerous place therefore
set w/t cor.

Set Brass cap for w/t cor S8° East
of true cor MRD

County Surveyors office
W.C. 509 West to
T 31 S R1W

533/534
54

T 32 S

1968

New Bearing Trees

10" Ash S 6 1/2 W 11'
Scribed W.C. T 32 S R1W S1 CS BT

9" Ash N 66 W 16'
Scribed W.C. T 31 S R1W S34 CS BT

Notes:

This car lies on top of creek
bank 250' south of fence line

7-29-68

#52 T 31-1

#200 O.W. J. W. B.

C.S. File No. 54/29-24

DIETZGEN NO. 385-B