

Renew E. $\frac{1}{4}$ S 59 | T 25 S R 8 W

Fd. Remains of Rock Mound decayed squared post, from which O.B.T.s are as follows -

ORIG. 14" Now 18" Laurel S. 30° W. 22 $\frac{1}{2}$ ft.
alive - we open & find " $\frac{1}{4}$ S 5 BT"
scribe & Reverse.

ORIG. 30" Now 40" Fir N. 50° W. 12 $\frac{5}{8}$ ft.
alive - shows very good scar - we do not open. - at cor. point set 1" I.P. & Brass cap 12" in ground & Build Rock mound around Pipe. MKd.

"COUNTY SURVEYOR'S OFFICE 1968
T 25 S $\frac{1}{4}$ S 5 | R 8 W" & MK. New B.T. -

10" D. Fir S. 2° W. 39° ft.

Mkd. " $\frac{1}{4}$ S 5 CS BT"

40" D. Fir N. 50° W. 12 $\frac{5}{8}$ ft. (O.B.T.)

Bark scribed. " $\frac{1}{4}$ S 5 CS BT" (above scar)

This cor. lies on very steep, rocky S.W. slope approx 80 ft. S. of Top of Rocky Ridge sloping S.E.

July 30, 1968

VRT
J.H.
U.P.

~~W.~~ G. Tracy

O.K. S. No. 54/72-9