

Renewal # 73 29 28
32 33 7305 R24

Founds
OBT's

36" D. Fir Now Stump N 31 E 53 E

20" D. Fir Now Stump N 65 S W 47 E
opened for searching "S" + other marks

24" D. Fir Now snag S 50 W 4 E
Shows good snag

30" D. Fir Now Down S 72 E 10 E
Shows good snag

Also
18" x 18" Stone + 1/2" x Pipe of Sec
car.

Renewal

New Bearing Trees
No Trees Available in burnt
Area.

Set (2) 6' steel fence Post East
8 E + 16 E

Note This car lies on top of
small ridge - about 15 E East
of and down fence line running
N + S

12-10-68

~~Signature~~

D.V.
J.V.B.

170

C.S. File No. 64/73-67

DIETZGEN NO. 388-6