

Renewal

514  
523

T295 R1W

Found:

30" D. Fir now 38" cor tree good scars  
on North & South Faces

20" cedar now 28" 529E 37°  
shows good scar.

36" D. Fir now 41" now 15-B  
Tree opened before pitched over strike  
visible

Renewal

Set Brass cap on East side of  
cor tree MKR

county Surveyors office  
T295 R1W

514  
A 523  
1969

RH BT's OK and Tagged.

1-3-69

~~1-3-69~~  
~~1-3-69~~  
~~1-3-69~~

O.K. J.W.D.

#27

C. S. File No. 54/82-9

DIETZGEN NO. 385-5