

Renewal R2W 1/4 530 R1W

Found: 2 bearing in excellent condition

No trace of basalt stone 20x6x6

10" S Pine now 16 N45°E 19 1/2 FT

Shows good scar and is good for bearing and DIST.

6" R FIR now 10" S42°E 25 1/2 FT

Shows good scar and is good for bearing and DIST.

NOTE Place yellow TAPS on both trees SET BRASS CAP AT BEARING and DIST FROM both BEARING TREES. (MKD)

COUNTY JURVEYORS Office

T295		
R	1/4	R
2	330	W
W	1969	W

NOTE: This 1/4 530 only lies south 33 1/2 FT from 1/4 525 only on the Range line of R1,2W of T295.

Plus these corners lie on steep west slope.

4/24/69

F.W.J

W.R.P. JR.

0.11
1/2
1/2

C.S. File No. 54/82-29

1/59 #451-2W

DIETZGEN NO. 385-6