Renewal CC S18/S19 T29S R1E

Found 20x10x10 corner stone in place
N&D. CC on East side, and Two Good
Bearing Trees
20 Cedar now 24" N33E 12.5
Shows Pool fake
6 Hemlock (now 8) S50E. I find Dist to obl. 18.6
Record 5.8
Shows Good Scribed S (T29S, 19)
Set Brass Cap at CC Corner from Bearing
and Dist. from

County Surveyors office

R 1 W S24 T29S S18/S19 R 1 E
CC
1969

Rescribed
24" Cedar N33E 12.5
Scribed (T29S R1E, 19 & 24 S)
Note This corner lies 21.3 South
of 1/4 S24 T29S R1W

5/21/69
FWJ
WRPJR.

O.M.
J.W.M

#22 #1 Var 20 to the East C. S. File No. 54/82-65

DIETZGEN NO. 385-6