

Benewah

522
527

T29S R1W

Found:

16" W. Oak now dead S57 $\frac{1}{2}$ E 103 $\frac{1}{2}$ E
stems good scars.

16" D. Fir now 22" NW 77 $\frac{1}{2}$ E
stems good scars.

Also Found~~d~~ chisled in bad
logs of River banks.
AS RECORDED

Benewah:

New Bearing Tree:

11" D. Fir 569E 118 $\frac{1}{2}$ E
scribed N 527 CS BT

Note:

No good place for witness cor.
as it is all bad rock or in
a low area.

This cor lies on the East
bank of South Umpqua River
also is visible from Road on
West River bank.

5-26-69

~~1222~~
~~1322~~
~~1422~~

O.K.
J.W.B.

#43

C.S. File No. 54/82-72

DIETZGEN NO. 385-6