

Renewal 15/19 T295 R1W

Found

19" D Fir new dead S 38 W 15°
shows good scar

29" D Fir new down N 52 E 5°
Tree Rotted

Also Stone 14 x 8 x 6 stone firmly
Set at 1/4 cor MKD 1/4 on West
Face.

Renewal

Set Brass cap at 1/4 cor MKD,
county Surveyors office

T295 R1W

1/4
S 15 / S 19

1969

New Bearing Trees

17" D. Fir S 87 1/2 W 29 E
Scribed 1/4 CS BT

18" D. Fir N 84° E 34 E
Scribed 1/4 CS BT

Scribing done with Axe

6-3-69

~~W.D.~~
~~M.D.~~
~~F.H.~~

PR 89/

C.S. No. 54/82-78