

Renew COR. # 26 of HES. 143 T295 R1E  
 Fd. STUMP of ORIG. 26" Now 32" FIR cor.  
 TREE - shows good SCAR - Q.B.T.S follows  
 ORIG. 26" Now 30" FIR N.  $1\frac{1}{2}^{\circ}$  E 10<sup>2</sup> ft.  
 Now Stump - shows good SCAR -  
 ORIG. 26" Now 32" FIR S.  $55^{\circ}$  E. 20<sup>5</sup> ft.  
 Now Stump - open & shows "BT" scribe  
 2<sup>o</sup> point 2<sup>o</sup> ft. west of center of  
 cor. Stump - set 1" I.P. & BRASS cap  
 MKd. "COUNTY SURVEYOR'S OFFICE  
 1969 T295 COR. # 26 | HES 143  
 R1E" MK. New B.T.S -  
 9" Maple S.  $43^{\circ}$  E. 21<sup>5</sup> ft.  
 MKd. "26 HES 143 CS BT"  
 16" D. FIR N.  $52^{\circ}$  E. 15<sup>2</sup> ft.  
 MKd. "26 HES 143 CS BT"  
 This cor. Lies 20 ft. East of  
 Cree K course S.E. & 27 foot of  
 Mountain - Bearings & Dist.'s To center of cor. STUMP

Dec. 17, 1969

V.R.T.  
 J.G.H.  
 V.D.P.

V.R.T. Tracy

O.K.  
 H.W.

#26

C.S. File No. 54/82-103