

SURVEYED FOR PROPERTY COR. RESTORATION
 LOCATED IN SECTION 9, T.27S., R.6W.W.M.
 SURVEYED FOR ORLO HANDY JUNE 20, 1967
 BY BAUGHMAN SURVEYING SERVICE
 SCALE 1" = 200'

REGISTERED
 OREGON
 LAND SURVEYOR

COUNTY SURVEYORS FILE DATA
 DO NOT REMOVE FROM OFFICE

Glenn S. Baughman

JULY 14, 1961
 GLENN S. BAUGHMAN
 1536

