

Xerox on tracing paper
sent to C. S.

RESTORED CORNER FOR STATE OF OREGON--DEPARTMENT OF FORESTRY

One quarter corner common to Sections 15 and 16, T23S, R10W, W.M.,
Coos and Douglas Counties, Oregon.

ORIGINAL

Fir post (missing) from which a:

- 10" Fir bears $SO\frac{1}{2}^{\circ}E$ 79 lks.: now 39" stump, in place, scribes $\frac{1}{4}$ visible.
- 8" Fir bears $N67^{\circ}W$ 69 lks.: now 36" stump, in place, face open, no scribes visible.

RESTORED

Set $1\frac{1}{2}$ " x 36" galvanized iron pipe with 3" bronze cap marked "OREGON
STATE BOARD OF FORESTRY $\frac{1}{4}$ S15 S16 1969 RS359", 34 inches in ground,
and from which a:

- 14" Fir bears $N83\frac{1}{2}^{\circ}E$ 25.4 ft. to face; scribed $\frac{1}{4}$ S15 BT RS359.
- 14" Fir bears $N30^{\circ}W$ 23.9 ft. to face; scribed $\frac{1}{4}$ S16 BT.

Set 4" x 4" x 72" white painted Cedar post 1.4 ft. S50W of corner
pipe. Oregon State Forestry Department metal location poster on
14" Fir BT N30W.

Dated December 3, 1969

Restored by Lloyd D. Smith under my direction.
Lloyd D. Smith, Transitman

REGISTERED
OREGON
LAND SURVEYOR

Arnold G. Gibson
NOV. 4, 1955
ARNOLD G. GIBSON
359

Present and witnessed by William E. Metcalf

FILED
RECEIVED

DEC 11 1969

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

O.K.
J. C. B.

#79

55/101-15