

RESTORED CORNER FOR STATE OF OREGON--DEPARTMENT OF FORESTRY

Section corner common to Sections 27, 28, 33, and 34,
Township 22 South, Range 12 West, Willamette Meridian,
Douglas County, Oregon.

ORIGINAL

4" x 4" x 4" Maple post (missing, found 1/2" iron pipe in place,) - *Ref 21*
from which a:

- 6" Elder bears N 40 E 48 lks.; missing.
- 6" Elder bears S 46 $\frac{1}{2}$ E 35 lks.; missing.
- 8" Maple bears S 61 $\frac{1}{4}$ W 29 lks.; missing, Maple root system in place.
- 36" Cedar bears N 42 W 24 lks.; now 70" in place, scribes 12W BT visible.
- Canyon, crs. SW, bears South 50 lks.; in place, creek in bottom.

RESTORED

Set 1 $\frac{1}{2}$ " x 36" galvanized iron pipe with 3" bronze cap marked "OREGON
STATE BOARD OF FORESTRY T22S R12W S27 S28 S33 S34 1969 RS 359",
34 inches in ground, over 1/2" iron pipe, and from which a:

- 70" Cedar (original) bears N 42 W 15.8 ft.; scribed RS 359.
- 20" Maple bears S20 W 50.2 ft. to face; scribed T22S R12W S33 BT.
- 59" Maple bears N 75 E 74.6 ft. to face; scribed T22S R12W S27 BT.
- 37" Hemlock bears S82E 110.1 ft. to face; scribed T22S R12W S34 BT.

Set 4" x 4" x 72" white painted Cedar post 1.2 ft. NW of corner pipe.
Oregon State Forestry Department metal location poster on 70" Cedar BT
N 42 W.

Dated February 11, 1969.

Restored by *Lloyd D. Smith* under my direction.
Lloyd D. Smith, Transitman

FILED
RECEIVED

MAY 20 1969

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

155

Present and witnessed by George Gresham
Dave Brown

