


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

$\frac{1}{4}$  corner was established in 1892 by W. P. Wright




Description of corner evidence found:

- Found 1" pipe from which
- 32" fir brs. S43 $\frac{1}{2}$ E 6.9 ft. (orig)  
face healed over, with tag
- 6" spruce brs. N31W 20.8 ft.  
scribing visible, with tag
- 20" spruce brs. N70W 23.9 ft.  
scribing visible, with tag

Description of monument and accessories established to perpetuate the original location of this corner

Set 2"x30" iron pipe with brass cap mkd



- Set 2 fence posts with signs  $\pm$  5 ft. east facing north
- $\pm$  5 ft. south facing west

#80

REGISTERED  
OREGON  
LAND SURVEYOR

*Tom O. McCullough*  
JULY 10, 1964  
TOM O. McCULLOUGH  
650

Office of SURVEYOR County of DOUGLAS  
State of OREGON, I hereby certify that the within instrument was filed in this office  
for record on the 13 day of MARCH, 1970, at 10 o'clock AM, (signed)

FILED

RECEIVED

(COUNTY OFFICIAL)

by

(DEPUTY)

MAR 13 1970

COUNTY SURVEYOR  
DOUGLAS COUNTY, ORE.