


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner established in 1892 by W.P. Wright

Re-established in February of 1970 by Douglas
County Surveyor



Description of corner evidence found:

Found pipe with brass cap mkd

T20S	
5 4	
8 9	CS office
R11W	
1970	from which

- 24" cedar brs. S32E 42.5 ft - scribed - with tag
- 34" alder brs. S60 $\frac{1}{2}$ W 31.5 ft - scribed - with tag
- Both set by County Surveyor
- 26" fir brs. N6E 74.5 ft - face pitched over - with BLM tag
- 36" cedar windthrow brs. N27W 66.0 ft (orig)
- Department of Interior tag

Description of monument and accessories established to perpetuate the original location of this corner

None

Set a fence post with signs \pm 5 ft west facing north

6/23/70 Added to Rem. #86
L.L.

Office of SURVEYOR County of DOUGLAS
 State of ORE, I hereby certify that the within instrument was filed in this office
 for record on the 23 day of JUNE; 1970, at 10 o'clock A.M., (signed)
James W. Ryan by _____ (DEPUTY)
 (COUNTY OFFICIAL)

FILED
RECEIVED

JUN 23 1970

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE
Form R6-7100-57 (9/66)

REGISTERED
OREGON
LAND SURVEYOR

Tom O. McCullough
 JULY 10, 1964
 TOM O. McCULLOUGH
 650

C. S. File No. 55/148-9