

RESTORED CORNER FOR STATE OF OREGON--DEPARTMENT OF FORESTRY

Northwest Section corner for Section 16, Township 22 South, Range 10 West, W.M., Douglas County, Oregon.

ORIGINAL

20" x 16" x 12" Sandstone (missing) from which a:

28" Fir bears N10°E 152 lks.; missing, in old burn and slide area.

10" Fir bears S37°E 57 lks.; now 40", in place, exposed scribes BT.

RESTORED

Set 1½" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY S17 S8 T22S R10W S16 1971 RS359", 34 inches in ground, in mound of rock, and from which a:

29" Fir bears N66½°E 34.2 ft. to face; scribed T22S R10W S16 BT.

40" (Orig.) Fir bears S37°E 37.6 ft.; scribed RS 359.

Set 4" x 4" x 72" white painted Cedar post 3.6 ft. S06°E of corner pipe. Oregon State Forestry Department metal location poster on 40" Fir BT.

Dated October 14, 1971

Restored by Lloyd D. Smith under my direction.
Lloyd D. Smith, Forest Engineer

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Arnold G. Gibson

OREGON
NOV 4, 1955
ARNOLD G. GIBSON
359

Present and witnessed by Charles W. Cook
Dale E. Redding
Kenneth Graham
William Bodewig

FILED
RECEIVED

FEB 3 1972

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

#61

C. S. File No. 55/233-2