

61
Ren

RESTORED CORNER FOR STATE OF OREGON--DEPARTMENT OF FORESTRY

One quarter corner for Section 25 (West side), T22S, R12W, W.M., Douglas County, Oregon.

ORIGINAL

12"x12"x3' Cedar post (missing) from which a:

- 15" Alder bears N74°E 39 lks.; missing.
- 24" Maple bears S52°E 40 lks.; missing.
- Ridge, course SE & NW, bears North 89 lks.; in place.

RESTORATION by Arnold G. Gibson 1969

1 1/2" x 36" galvanized iron pipe with 3" bronze cap (found out of place) from which a:

- 17" Cedar bears S60°E 15.0 ft.; now 20" stump, scribes 1/4 S25 BT RS 359 visible in partially closed face.
- 24" Cedar bears S41°E 44.6 ft.; now missing, in road construction.
- 4"x4"x72" white painted cedar post bears Northwest 2.0 ft.; now missing, in road construction.

RESTORED

Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY 1/4 S25 1969 RS 359", 35 inches in ground, and from which a:

- 17" Cedar bears N66°E 52.1 ft. to face; scribed 1/4 S25 BT.
- 50" Fir bears N10°E 58.9 ft. to face; scribed 1/4 S25 BT RS 359.
- Center Wilkins Ridge Road (course NW & SE) bears North 23.0 ft.

Set 4" x 4" x 72" white painted Cedar post 6.0 ft. N37°E of corner pipe. Oregon State Forestry Department metal location poster on 17" Cedar BT N66°E 52.1 ft.

Dated May 30, 1972

Restored by Rodney T. Shepard under my direction.
Rodney T. Shepard, Transitman

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Arnold G. Gibson

OREGON
NOV 4, 1955
ARNOLD G. GIBSON
359

Present and witnessed by Charles W. Cook
Steven M. Conover
Steven A. Nicholson
Dale E. Redding

FILED
RECEIVED

MAY 19 1972

COUNTY SURVEYOR
DOUGLAS COUNTY, OREGON

#100 ✓