

RESTORED CORNER FOR STATE OF OREGON--DEPARTMENT OF FORESTRY

One quarter corner common to Sections 10 and 15, T23S, R10W, W.M., Douglas County, Oregon.

ORIGINAL

Post (missing) from which a:

- 10" Fir bears S07°E 30 lks.; now 52" stump in place, face grown over.
- 10" Fir bears N48°W 85 lks.; now 42" stump in place, exposed scribes 1/.

RESTORED

Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY 1/4 S10 S15 1971 RS 359", 34 inches in ground, and from which a:

- 19" Fir bears S56 1/2°E 77.6 ft. to face; scribed 1/4 S15 BT RS 359.
- 15" Fir bears N62°E 62.5 ft. to face; scribed 1/4 S10 BT.

Set 4" x 4" x 72" white painted Cedar post 4.5 ft. N45°W of corner pipe. Oregon State Forestry Department metal location poster on 19" Fir BT S56 1/2°E 77.6 ft.

Dated May 30, 1972

Restored by Charles W. Cook under my direction.
Charles W. Cook, Engineer



Present and witnessed by Mark E. Cook
Steven M. Conover
Steven A. Nicholson

FILED
RECEIVED

AUG 16 1972

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.