

RESTORED CORNER FOR STATE OF OREGON--DEPARTMENT OF FORESTRY

Angle point corner for old North 1/4 of Section 2, Township 23 South, Range 11 West, W.M., Coos and Douglas Counties, Oregon.

ORIGINAL

8" Alder (now missing) from which a:

- 8" Fir bears N23°E 40 lks.; now 23", in place, scribes BT P exposed.
- 50" Dead Fir bears S07°W 100 lks.; missing, in small slide area.

RESTORED

Set 1½" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY S2 T23S R11W AP 1971 RS359", 34 inches in ground, and from which a:

- 20" Fir bears N27°W 45.7 ft. to face; scribed AP S35 BT RS359.
- 19" Fir bears S03°W 14.9 ft. to face; scribed AP S2 BT.

Set 4" x 4" x 72" white painted Cedar post 2.2 ft. N65°W of corner pipe. Oregon State Forestry Department metal location poster on 19" Fir BT S03°W 14.9 ft.

Dated October 12, 1971

RESTORED BY Charles W. Cook
Charles W. Cook, Engineer

under my direction.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Arnold G. Gibson

OREGON
NOV 4 1955
ARNOLD G. GIBSON
359

Present and witnessed by William A. Bodewig
Dale E. Redding

FILED
RECEIVED

FEB 3 1972

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

SEE M 45-3

~~116~~
O # 116 T22-11

C. S. File No. 55/233-1A