

RESTORED CORNER FOR STATE OF OREGON--DEPARTMENT OF FORESTRY

Angle point corner common to Sections 36 and 31 (original corner 30, 31, 25 & 36), T32S, R4&5W, W.M., Douglas County, Oregon.

T32-4
T32-5

ORIGINAL

Post (missing) from which a:

- 8" Fir bears S25°W 18 lks.; missing.
- 12" Fir bears S50°E 73 lks.; missing (destroyed by Nicklin 1896), root holes in place.
- 6" Fir bears N66°E 43 lks.; missing (destroyed by Nicklin 1896), covered by fresh logging slash.
- 12" Hemlock bears N40°W 20 lks.; missing.

RESTORATION by Carl S. Nicklin 1896.

Post (missing). See above for SW and NW Bts.

RESTORATION by Oscar F. Thiel 1900.

Hemlock post (missing) from which a:

- 24" Fir bears N22°E 86 lks.; now 16"x10' rotten stub, in place, no face.
- 40" Fir bears S83°E 12 lks.; now 46" windfall snag, found back cast B and scribes SW.

RESTORATION (not recorded)

17" White Fir bears N56°W 54.0 ft.; face opened, scribes T32 S R5W S visible at 50 years.

RESTORED

Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY AP T32S S36 R5W T32S S31 R4W 1972 RS 359", 34 inches in ground, and from which a:

- 11" Fir bears N44°E 15.2 ft. to face; scribed T32S R4W S31 AP BT.
- 10" Fir bears N80°W 20.1 ft. to face; scribed T32S R5W S36 AP BT RS 359.

Set 4" x 4" x 72" white painted Cedar post 2.5 ft. S44°E of corner pipe. Oregon State Forestry Department metal location poster on 11" Fir N44°E 15.2'. Also poster on 10" Fir N80°W 20.1'.

Dated May 30, 1972

Restored by Lloyd D. Smith under my direction.
Lloyd D. Smith, Forest Engineer

Present and witnessed by Steven M. Conover
✓ Marvin D. Pounds

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Arnold G. Gibson
OREGON
NOV 4, 1955
ARNOLD G. GIBSON
359

FILED
RECEIVED

AUG 16 1972

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.