



THE ROBERT DOLLAR CO.

FOREST PRODUCTS DIVISION

TELEPHONES

Area Code 503

OFFICE: 832-2111 SALES: 832-2131

GLENDALE, OREGON 97442

June 19, 1972

HEAD OFFICE
311 CALIFORNIA STREET
SAN FRANCISCO 94104

County Surveyors Office
Douglas County Courthouse
Roseburg, Oregon 97470

Dear Mr. Ingram:

It will be necessary to cut one bearing tree damaged in logging on the $\frac{1}{4}$ corner, Sec. 9 and 16, T. 32 S., R. 9 W., W.M. The corner was found as follows:

Brass Cap, set 1917 by G.L.O.

old 9" hemlock stub, N 85° E, 16.0' pushed over.

14" hemlock, N 34° E, 11.8' now 15.6" DBH.

16" hemlock, S 53° E, 12.0 now 19.2" DBH to be felled.

The following tree was scribed and bears from the brass cap:

22" DBH hemlock, S 37° 30' E, 31.27'
marked $\frac{1}{4}$ S 16 PE 6803 BT

Magnetic variation noted to match bearings of existing B.T.'s was 22° E.

Very truly yours,
THE ROBERT DOLLAR CO.

Ronald A. Brandt

Ronald A. Brandt, P.E. 6803

FILED *LL*
RECEIVED

JUN 20 1972

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

#73

C. S. File No. 55/257-1