

RESTORED CORNER FOR STATE OF OREGON-DEPARTMENT OF FORESTRY

Section corner for Section 31 (SW), Township 22 South, Range 10 West, W.M., Douglas and Coos Counties, Oregon.

ORIGINAL

20" x 12" x 8" stone (in place, no marks visible) from which a:

- 36" Fir bears N73°E 44 lks.; now 50" rotten snag 30' tall, in place, no marks visible.
- 30" Fir bears S24°W 12 lks.; now 28" rotten stub in place, scribes S31 B visible.
- 40" Fir bears N55°W 29 lks.; now missing.

RESTORED

Set 1½" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T22S R10W S31 T23S R11W S1 1971 RS359", 35 inches in ground, with original stone along side, and from which a:

- 22" Fir bears N42°E 10.6 ft. to face; scribed T22S R10W S31 BT RS359.
- 33" Fir bears N09°W 10.6 ft. to face; scribed T22S R10W S31 BT.

Set 4" x 4" x 72" white painted Cedar post 2.7 ft. S01°W of corner pipe. Oregon State Forestry Department metal location poster on 33" Fir BT.

Dated November 22, 1971

Restored by Charles W. Cook under my direction.
Charles W. Cook, Engineer

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Arnold G. Gibson

OREGON
NOV 4 1955
ARNOLD G. GIBSON
359

Present and witnessed by Dale E. Redding
Kenneth L. Graham

FILED
RECEIVED

AUG 16 1972.

COUNTY SURVEYOR
DOUGLAS COUNTY

C. S. File No. 55/265-1

#68 T22-10 ✓
#87 T23-10