

RESTORED CORNER FOR STATE OF OREGON--DEPARTMENT OF FORESTRY

Angle point corner for Section 1 (originally 1/4 corner for Sec. 1), Township 23 South, Range 11 West, W.M., Coos County, Oregon.

ORIGINAL

17" x 12" x 6" Stone (badly sluffed 4" x 10" x 10" stone found in place) from which a:

- 50" Burnt Fir bears N20°E 38 lks.; now 47" x 20' high Fir snag in place.
- 40" Burnt Fir bears S41°W 31 lks.; now rotted root system, 30' rotted log on ground.

RESTORED

Set 1½" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY AP S1 T23S R11W 1971 RS359", 35 inches in ground, with original stone alongside, and from which a:

- 28" Fir bears S38½°E 21.4 ft. to face; scribed T23S R11W S1 AP BT.
- 25" Fir bears S14°W 11.0 ft. to face; scribed T23S R11W S1 AP BT RS359.

Set 4" x 4" x 72" white painted Cedar post 2.3 ft. S11°W of corner pipe. Oregon State Forestry Department metal location poster on 25" Fir S14°W 11.0 ft.

Dated November 24, 1971

Restored by Lloyd D. Smith under my direction.  
Lloyd D. Smith, Forest Engineer

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*Lloyd D. Smith*  
OREGON  
NOV 4, 1955  
ARNOLD G. GIBSON  
359

Present and witnessed by Charles W. Cook  
Kenneth L. Graham  
Dale E. Redding

FILED  
RECEIVED

AUG 16 1972

COUNTY SURVEYOR  
DOUGLAS COUNTY, ORE.

C.S. File No. 55/26512

# 123-722-11 ✓  
~~TR 359~~