

RESTORED CORNER FOR STATE OF OREGON--DEPARTMENT OF FORESTRY

Angle point corner for old North 1/4 of Section 2, Township 23 South, Range 11 West, W.M., Coos and Douglas Counties, Oregon.

ORIGINAL

8" Alder (now missing) from which a:

- 8" Fir bears N23°E 40 lks.; now 23", in place, scribes BT P exposed.
- 50" Dead Fir bears S07°W 100 lks.; missing, in small slide area.

RESTORED

Set 1½" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY S2 T23S R11W AP 1971 RS359", 34 inches in ground, and from which a:

- 20" Fir bears N27°W 45.7 ft. to face; scribed AP S35 BT RS359.
- 19" Fir bears S03°W 14.9 ft. to face; scribed AP S2 BT.

Set 4" x 4" x 72" white painted Cedar post 2.2 ft. N65°W of corner pipe. Oregon State Forestry Department metal location poster on 19" Fir BT S03°W 14.9 ft.

Dated October 12, 1971

RESTORED BY Charles W. Cook under my direction.  
Charles W. Cook, Engineer

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*Ronald L. Gibson*  
OREGON  
NOV 4. 1955  
ARNOLD G. GIBSON  
359

Present and witnessed by William A. Bodewig  
Dale E. Redding

FILED  
RECEIVED

FEB 3 1972

COUNTY SURVEYOR  
DOUGLAS COUNTY, ORE.

# ~~20-11~~  
O # 116 T22-11

MAP FILE M45-3  
C. S. File No. 55/265 Copies 55/233  
C. S. File No. 55/233