

FILED  
RECEIVED

NOV 10 1972

COUNTY SURVEYOR  
DOUGLAS COUNTY, ORE.

RESTORED CORNER FOR STATE OF OREGON--DEPARTMENT OF FORESTRY

Section corner common to Sections <sup>10</sup> 11 and 15, Township 23 South,  
Range 10 West, W.M., Douglas County, Oregon.

ORIGINAL

Post (missing) from which a:

- 24" Fir bears S9°E 85 lks.; now 63" in place, face burned away.
- 24" Fir bears S57°W 63 lks.; now 46" in place, exposed scribes T and parts of backcast on burnt face.

RESTORED

Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY S10 S15 S11 T23S R10W 1972 RS359", 34 inches in ground, and from which a:

- 13" Fir bears S26 1/2°W 76.2 ft. to face; scribed T23S R10W S15 BT RS 359.
- 56" Fir bears S84°E 40.1 ft. to face; scribed T23S R10W S11 BT.

Set 4" x 4" x 72" white painted Cedar post 2.6 ft. S64°E of corner pipe. Oregon State Forestry Department metal location poster on 56" Fir BT S84°E 40.1 feet.

Dated October 13, 1972

Restored by Charles W. Cook under my direction.  
Charles W. Cook, Engineer

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*Arnold G. Gibson*

OREGON  
NOV 4. 1955  
ARNOLD G. GIBSON  
359

Present and witnessed by Rodney T. Shepard  
William E. Metcalf