

ROSEBURG

LUMBER CO.

P.O. BOX 1088 · ROSEBURG, OREGON 97470 PHONE (503) 679-8741

April 18, 1973

To: Douglas County Surveyor

New B. T. for N $\frac{1}{4}$ cor. Section 32, T. 27 $\frac{1}{2}$ S., R8W. W.M.

Found: Brass Cap marked $\frac{1}{4}$ S 32
T27 $\frac{1}{2}$ S., R8W.
1961

Orig. B.T.'s:

A Cedar. 22 ins. dia. S72 $\frac{1}{2}$ $^{\circ}$ E. 46 Lks.
Scribe visible but now a shattered stump.

A Hemlock 40 ins. dia. S36 $^{\circ}$ W. 107 Lks.
Scribe not visible now a stump.

New B. T.

Scribed: 6 in. dia. YEW S41 $^{\circ}$ E. 17.7ft.
" $\frac{1}{4}$ S. 32 B.T."

All of Section 32 has been clear cut. There are no other trees suitable for bearing trees.

Howard W. Johnstone
Logging Engineer

HWJ/jt

FILED
RECEIVED


APR 19 1973

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

✓ #9-27 $\frac{1}{2}$ -8
✓ #28-27-8



Howard W. Johnstone



C. S. File No. 55/286