

FILED *L*
RECEIVED

JUN 28 1973

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

RESTORED CORNER FOR STATE OF OREGON -- DEPARTMENT OF FORESTRY

One quarter corner common to Sections 17 and 20, Township 22 South,
Range 10 West, W.M., Douglas County, Oregon.

ORIGINAL

4" Alder (missing) from which a:

- 4" Fir bears South 3 lks.; now 13" x 9' tall stub, in place, scribes 1/4S exposed.
- 6" Fir bears N15°E 13 lks.; now 5" x 18" long rotted chunk, out of place, scribes BT remaining.

RESTORED

Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY 1/4 S17 S20 1973 RS359", 35 inches in ground, and from which a:

- 20" Fir bears S42 1/4°W 12.0 ft. to face; scribed 1/4 S20 BT RS359.
- 34" Fir bears N46 1/2°E 17.6 ft. to face; scribed 1/4 S17 BT.

Set 4" x 4" x 72" white painted Cedar post 1.7 feet East of corner pipe. Oregon State Forestry Department metal location poster on 34" Fir BT N46 1/2°E 17.6 feet.

Dated May 3, 1973

Restored by *Charles W. Cook* under my direction.
Charles W. Cook, Engineer

Present and witnessed by William E. Metcalf
Michel S. Reed

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Arnold G. Gibson
OREGON
NOV 4 1955
ARNOLD G. GIBSON
359

#69 ✓