

**ROBERT M. THOMPSON**  
Consulting Engineer and Forester

Dependent Resurvey of That Land Shown as Tract No. 14  
in County Surveyor's Map File No. M42-37, in SW $\frac{1}{4}$  Section  
11 and NW $\frac{1}{4}$  Section 14, T 32S, R5W, W.M., Douglas County, Oregon

Narrative description to comply with Par. 209.250, O.R.S.

for: Harry O. Clendenin, P.O. Box 165, Azalea, Oregon

Purpose: To check and/or set angle point corners (some of which  
appeared to client to have been moved or displaced),  
and mark boundaries.

Procedure:

From an examination of existing records, it appeared that  
the deed description for the Clendenin property had been written  
from information shown on said survey map No. M42-37. My bearing  
basis was taken from open and direct sighting of existing mon-  
uments along Mobley Drive (per record), since the pertinent  
property was nearly all in timber and brush, and the northeast-  
erly boundary appeared to have never been physically surveyed  
on the ground.

My survey commenced with a closed traverse around the  
Clendenin property, also tying in all pertinent existing monuments  
that could be found. Three of the angle point monuments found  
were far out of place, or not the originals. The rest checked  
out closely with record positions, bearings and distances. Hold-  
ing to the apparent intent of the deed, my survey was completed  
by using record or slightly adjusted and proportioned bearings  
and distances, between those found monuments which appeared to  
be in the original positions. Additional monuments were set  
as shown on my map. The true boundaries were then marked with  
red-painted blazes and flagging.

August 31, 1973

