

Not Found SE | T26SR4W
corner DLC #43

corner falls in open area
no trace of Iron pipe
or bearing Trees.

Found & o.k. $\frac{1}{4}$ $\frac{34}{3}$ T26SR4W
T27SR4W

Rem #35 - Axel & bearing trees
in good condition
Rem #67-T27-4 ✓ ✓

o.k.
J.W. B

J. Byron
W. Penley
J. Heritage

1-27-71

C.S. No. 56/1-9