

53
Renewal #32 — 532 T25S R7W
— 55 T26S R7W

Found

30" D. Fir Now 35" S33E 8.0

Shows good scar

16" basal Now 18" N18 $\frac{1}{2}$ W 129

Bark scribe visible

2807 - 532 T25S R7W BT

Renewal

Drive $\frac{5}{8}$ " I Rod at 400r

New Bearing Tree

9" D. Fir S 27 W 65

scr. led $\frac{1}{4}$ S S CS BT

#104 T25-7 ✓
#91 T26-7 ✓

O.K.
J.P.L.

2-14-73

J.P.L.
J.P.L.
J.P.L.

C.S. File No. 56/25-3