


Section 14 748 Twp 29S Rge 1E W

Date: \_\_\_\_\_



How was corner identified? \_\_\_\_\_

Condition of corner: \_\_\_\_\_

Best route to reach corner: \_\_\_\_\_

Road " 2815

C.S. File No. 56/40-34

Quadrant	NE	NW	SE	SW
Species & Size				
Dist. & Bearing				
Condition of Scribe				
Original or Resurvey				
Appearance of B.T.				
Tags, Marks, etc.				

Other Remarks:

Could have been destroyed by  
logging.

Signed \_\_\_\_\_

