


Section 1/4 7418 Twp 30 S Rge 1 E W

Date: _____

How was corner identified? NEVER FOUND

Condition of corner: _____

Best route to reach corner: ROAD #284 OR 2929



C. S. FILE NO. 56/40-47

Quadrant	NE	NW	SE	SW
Species & Size				
Dist. & Bearing				
Condition of Scribe				
Original or Resurvey				
Appearance of B.T.				
Tags, Marks, etc.				

Other Remarks:

Signed

NO VISUAL
PAGE