


Section 1/4 8417 Twp 29S Rge 1E W

Date: 2-15-45



How was corner identified? BRASS CAP

Condition of corner: _____

Best route to reach corner: Road 2826

C. S. File No. 56/40-49

Quadrant	NE	NW	SE	SW
Species & Size		24"	SP 36"	
Dist. & Bearing		84° 14' 13"	S 2 E 22' 13"	
Condition of Scribe				
Original or Resurvey				
Appearance of B.T.				
Tags, Marks, etc.			Tagged	

Other Remarks:

Signed

#39 ✓
c