


Section 1/4 847 Twp 29S Rge 1E W 1 Date: NO DATE



How was corner identified? BRASS CAP

Condition of corner: _____

Best route to reach corner: ROAD # 2826

C. S. File No. 140-50

Quadrant	NE	NW	SE	SW
Species & Size				
Dist. & Bearing				
Condition of Scribe				
Original or Resurvey				
Appearance of B.T.				
Tags, Marks, etc.				

Other Remarks: NO INFO ON RT'S

Signed #40
 c