

Section 1/4 9410 Twp 29S Rge 1E W

Date: 6-17-59



How was corner identified? BRASS CAP

Condition of corner: _____

Best route to reach corner: ROAD # 272, A or B

C. S. File No. 56/40-51

Quadrant	NE	NW	SE	SW
Species & Size				
Dist. & Bearing				
Condition of Scribe				
Original or Resurvey				
Appearance of B.T.				
Tags, Marks, etc.				

Other Remarks:

Could be in C.C.

Signed

#41 ✓
C