


Section 1/4 10911 Twp 29 S Rge 1 E W

Date: 4-7-61



How was corner identified? BRASS CAP

Condition of corner: \_\_\_\_\_

Best route to reach corner: Road # 224

C. S. File No. 5648-5B

Quadrant	NE	NW	SE	SW
Species & Size				
Dist. & Bearing				
Condition of Scribe				
Original or Resurvey				
Appearance of B.T.				
Tags, Marks, etc.				

Other Remarks:

NO INFO ON B.T.S  
Could be in CC.

Signed

#13 ✓  
c