


Section 11 & 14 Twp 29S Rge 1E W

Date: 4-22-69



How was corner identified? BRASS CAP

Condition of corner: _____

Best route to reach corner: ROAD 294.2

C.S. File No. 56/40-55

Quadrant	NE	NW	SE	SW
Species & Size				
Dist. & Bearing				
Condition of Scribe				
Original or Resurvey				
Appearance of B.T.				
Tags, Marks, etc.				

Other Remarks:

New BT need
FOR SEC 14

Signed

#45
c